

UDUPI NIRMITHI KENDRA .(R)
D.C.Office,Manipal

Date: 01/03/2021

VALUATION
FIRST & PART VALUATION

Name Of Work : ಉಡುಪಿ ಜಿಲ್ಲೆ ಬೃಹದ್ವರ ತಾಲೂಕು ಸಾಸ್ತನ ಕೋಡಿ ರಸ್ತೆಯಿಂದ ಮಣಾರು ಮೀನುಗಾರಿಕಾ ರಸ್ತೆ
ಅಭಿವೃದ್ಧಿ ಕಾಮಗಾರಿ.

Head of account : ಮೀನುಗಾರಿಕಾ ಇಲಾಖೆ - ಬೆಂಗಳೂರು

Estimate Amount : ₹.146,00,000.00

Released Amount by department ₹.146,00,000.00

Upto Date Valuation Amount ₹.120,11,863.00

Previous Valuation Amount -


Prasent Valution Amount(First & Part Valution) ₹ 120,11,863.00

Date of Commencement : 15/11/2020


Administrative Approval No.: ಪನಂಮೀ ಇ 95/ ಮೀಇಯೋ/2019-2 - ಬೆಂಗಳೂರು


Third party consultant : MIT, MOODLUKATTE, KUNDAPUARA, UDUPI.

Date:12/11/2020


Principal
Moodlakatte Institute of Technology
Moodlakatte, Kundapura - 576217
Udupi Dist, Karnataka


Project Engineer
Udupi Nirmithi Kendra.(R)
Udupi Nirmithi Kendra


Project Director
PROJECT DIRECTOR
Udupi Nirmithi Kendra.(R)
Udupi Nirmithi Kendra



Moodlakatte Institute of Technology

(A Unit of Moodlakatte Nagarathna Bhujanga Shetty Trust (R.))

(Approved by AICTE, New Delhi & Affiliated to V.T.U., Belagavi)


Moodlakatte - 576 217, Kundapura Taluk, Udupi District, Karnataka


A WIDE
HORIZON OF
OPPORTUNITIES
Date : 08/03/2021


Ref.No.: MITK/CV/CW/20-21/NK/03/002


INSPECTION/ WORK PROGRESS REPORT (1st & Part Valuation)

1	Name of the ULB	NIRMITHI KENDRA (UDUPI) DEPARTMENT OF FISHERIES - BANGALORE
2	Name of the Work/ Scheme	DEVELOPMENT WORK OF ROAD FROM SASTHANA KODI ROAD MANURU FISHERIES ROAD, AT BRAHMAVARA TALUK UDUPI DISTRICT.
3	Administrative Approval No: / Agreement No.	E95/ME. E. YO/2019-20 BANGALORE Dtd: 12./11/2020
4	Technical Sanction No/ DER No.	
5	Estimate Cost	Rs.1,46,00,000.00/-
6	Bill Amount	Rs.1,20,11,863.00/-
7	Name of the ULB Engineer present at site	Mr. GANESH PRASAD SHETTY
8	Name of the contractor	NIRMITHI KENDRA UDUPI
9	Name of the inspecting consultants Engineer	Mr. SUBRAMANYA P
10	Date of commencement of the work	15/11/2020
11	Date of Completion	UNDER PROGRESS
12	Date of the Inspection	03/12/2020, 21/01/2021, 06/03/2021
13	Status of the Work	COMPLETED
14	Details of Quality tests carried out by consultants	Inspected the work no major deficiency were found and quality of the work is satisfactory.
15	Photographs of the works along with date of inspection on the photo	Attached
16	Consultant clear opinion regarding acceptance of the quality of work.	We have inspected the site and observed that work is done according to the norms and specification mentioned
17	If the quality of work is not up to the satisfactory, the consultants suggestions for rectifications/ redoing	No Suggestions, Work is done satisfactorily
18	Measurement Book No. in which the measurement recorded	MB No- Pg. No -
19	Opinion of the Third Party agency regarding measurement	Measurement checked as per the estimation copy and found to be correct.


Principal & Head, Civil Department
MOODLAKATTE INSTITUTE OF TECHNOLOGY
Moodlakatte, Kundapura - 576 217
Udupi Dist., Karnataka


Principal
Moodlakatte Institute of Technology
Moodlakatte, Kundapura - 576217
Udupi Dist, Karnataka





UDUPI NIRMITHI KENDRA .(R)
D.C.Office,Manipal
RUNNING ACCOUNT BILL

Date: 25-05-21

FIRST & FINAL BILL

Name of Project : ಶಾಸಕರ ಸ್ಥಳೀಯ ಪ್ರದೇಶಾಭಿವೃದ್ಧಿ ಯೋಜನೆ 2020-21

Bill No. : 31/2021-22

Amount : 400,000.00

Name Of Work (As per Sactioned Estimate) : ಉಡುಪಿ ಜಿಲ್ಲೆ ಕುಂದಾಪುರ ವಿಧಾನಸಭಾಕ್ಷೇತ್ರದ ಸಾಲಿಗ್ರಾಮ ಪಟ್ಟಣ ಪಂಚಾಯತ್ ವ್ಯಾಪ್ತಿಯ ಸಾಲಿಗ್ರಾಮ ಬಸ್ ನಿಲ್ದಾಣದ ಬಳಿ ರಿಕ್ವಾ ಸ್ಟ್ರಾಂಡ್ ರಚನೆ .

Estimate Amount : 400,000.00

Date of Commencement : 18-04-21

Date of Completion : 24-05-21

Administrative Approval No. : ಕೆ.ಎಲ್. ಎಲ್.ಎ.ಡಿ ಸಿ ಆರ್ DC UDP-
18011(12)/27/2021/62755

Date: 17-03-21

Amount Rs. : 400,000.00

Technical Sanction No. : 240/2020-21

Date: 15-02-21

Amount Released for the work up to date from the entrusting agency .

Certified the works referred to above have been checked and the measurements taken by me on 24-05-2021 and recorded on Pages 01- 08 Of Measurement Book no 1151 Has been correctly complied and work has been satisfactorily executed.

Project Engineer
Udupi Nirmithi Kendra.(R)

Certified that the Running Account Bill no. 31 Has been Checked by me are found correct. The work has been satisfactorily executed.

Moodlakatte Institute of Technology
Moodlakatte, Kundapura - 576217
Udupi Dist, Karnataka

Project Director
Udupi Nirmithi Kendra.(R)




Moodlakatte Institute of Technology

(A Unit of Moodlakatte Nagarathna Bhujanga Shetty Trust (R.))

(Approved by AICTE, New Delhi & Affiliated to V.T.U., Belagavi)

Moodlakatte - 576 217, Kundapura Taluk, Udupi District, Karnataka

Ref.No.: MITK/CV/CW/21-22/NK/06/007




INSPECTION/ WORK COMPLETION REPORT (1st & Final Bill)

1	Name of the ULB	NIRMITHI KENDRA (UDUPI) NATURAL DISASTER GRANT
2	Name of the Work/ Scheme	CONSTRUCTION WORK OF AUTO STAND NEAR SALIGRAMA BSU STAND AT SALIGRAMA TP, KUNDAPURA CONSTITUENCY, UDUPI DISTRICT.
3	Administrative Approval No: / Agreement No.	CR DC UDP: 18011(12)27/2021/62755 Dtd: 17/03/2021
4	Technical Sanction No/ DER No.	240/2020-21
5	Estimate Cost	Rs.4,00,000.00/-
6	Bill Amount	Rs.4,00,000.00/-
7	Name of the ULB Engineer present at site	Mr. MAHESH KUMAR SHETTY
8	Name of the contractor	NIRMITHI KENDRA UDUPI
9	Name of the inspecting consultants Engineer	Mr. SUBRAMANYA P
10	Date of commencement of the work	18/04/2021
11	Date of Completion	24/05/2021
12	Date of the Inspection	29/05/2021
13	Status of the Work	COMPLETED
14	Details of Quality tests carried out by consultants	Inspected the work no major deficiency were found and quality of the work is satisfactory.
15	Photographs of the works along with date of inspection on the photo	Attached
16	Consultant clear opinion regarding acceptance of the quality of work.	We have inspected the site and observed that work is done according to the norms and specification mentioned
17	If the quality of work is not up to the satisfactory, the consultants suggestions for rectifications/ redoing	No Suggestions, Work is done satisfactorily
18	Measurement Book No. in which the measurement recorded	MB No- 1151 Pg No – 01-08
19	Opinion of the Third Party agency regarding measurement	Measurement checked as per the estimation copy and found to be correct.

Professor & Head, Civil Department
MOODLAKATTE INSTITUTE OF TECHNOLOGY
Moodlakatte, Kundapura - 576 217
Udupi Dist., Karnataka

Principal
Moodlakatte Institute of Technology
Moodlakatte, Kundapura - 576217
Udupi Dist, Karnataka





Moodlakatte Institute of Technology

(A Unit of Moodlakatte Nagarathna Bhujanga Shetty Trust (R.))

(Approved by AICTE, New Delhi & Affiliated to V.T.U., Belagavi)

Moodlakatte - 576 217, Kundapura Taluk, Udupi District, Karnataka


Ref No.: MITK/CV/CW/20-21/NK/03/001


Date: 08/03/2021





INSPECTION/ WORK PROGRESS REPORT (1st & Part Valuation)

1	Name of the ULB	NIRMITHI KENDRA (UDUPI) DEPARTMENT OF FISHERIES - BANGALORE
2	Name of the Work/ Scheme	DEVELOPMENT WORK OF ROAD FROM SASTHANA KODI ROAD 3395.00 METERS TO 4445.00 METERS AT MANURU FISHERIES ROAD, BRAHMAVARA TALUK UDUPI DISTRICT.
3	Administrative Approval No: / Agreement No.	E95/ME. E. YO/2019-20 BANGALORE Dtd: 12./11/2020
4	Technical Sanction No/ DER No.	
5	Estimate Cost	Rs.1,95,00,000.00/-
6	Bill Amount	Rs.1,40,52,236.00/-
7	Name of the ULB Engineer present at site	Mr. GANESH PRASAD SHETTY
8	Name of the contractor	NIRMITHI KENDRA UDUPI
9	Name of the inspecting consultants Engineer	Mr. SUBRAMANYA P
10	Date of commencement of the work	15/11/2020
11	Date of Completion	UNDER PROGRESS
12	Date of the Inspection	03/12/2020, 21/01/2021, 06/03/2021
13	Status of the Work	COMPLETED
14	Details of Quality tests carried out by consultants	Inspected the work no major deficiency were found and quality of the work is satisfactory.
15	Photographs of the works along with date of inspection on the photo	Attached
16	Consultant clear opinion regarding acceptance of the quality of work.	We have inspected the site and observed that work is done according to the norms and specification mentioned
17	If the quality of work is not up to the satisfactory, the consultants suggestions for rectifications/ redoing	No Suggestions, Work is done satisfactorily
18	Measurement Book No. in which the measurement recorded	MB No-Pg. No -
19	Opinion of the Third Party agency regarding measurement	Measurement checked as per the estimation copy and found to be correct.


Principal & Head, Civil Department
MOODLAKATTE INSTITUTE OF TECHNOLOGY
Moodlakatte, Kundapura - 576 217
Udupi Dist., Karnataka


Principal
Moodlakatte Institute of Technology
Moodlakatte, Kundapura - 576217
Udupi Dist, Karnataka





UDUPI NIRMITHI KENDRA .(R)
D.C.Office,Manipal

Date: 01/03/2021

VALUATION
FIRST & PART VALUATION

Name Of Work : ಉಡುಪಿ ಜಿಲ್ಲೆ ಬೃಹ್ಮಾವರ ತಾಲೂಕು ಸಾಸ್ತನ ಕೋಡಿ ರಸ್ತೆಯಿಂದ 3395.00 to 4445.00 ಮೀ ತನಕ ಮಣ್ಣು ಮೀನುಗಾರಿಕಾ ರಸ್ತೆ ಅಭಿವೃದ್ಧಿ ಕಾಮಗಾರಿ.

Head of account : ಮೀನುಗಾರಿಕಾ ಇಲಾಖೆ - ಬೆಂಗಳೂರು

Estimate Amount : ₹.195,00,000.00

Released Amount by department ₹.195,00,000.00

Upto Date Valuation Amount ₹.140,52,236.00

Previous Valuation Amount -


Prasent Valuation Amount(First & Part Valuation) ₹ 140,52,236.00


Date of Commencement : 15/11/2020


Administrative Approval No. : ವನಂಮೀ ಇ 95/ ಮೀಇಯೋ/2019-2 - ಬೆಂಗಳೂರು

Date:12/11/2020

Third party consultant : MIT, MOODLUKATTE, KUNDAPUARA, UDUPI.


Principal
Moodlakatte Institute of Technology
Moodlakatte, Kundapura - 576217
Udupi Dist, Karnataka


Project Engineer
Udupi Nirmithi Kendra.(R)
Udupi Nirmithi Kendra


Project Director
Udupi Nirmithi Kendra.(R)
Udupi Nirmithi Kendra



UDUPI NIRMITHI KENDRA .(R)
D.C.Office,Manipal
RUNNING ACCOUNT BILL

Date: 18-09-20

FIRST & FINAL BILL

Name of Project : ಪ್ರಾಕೃತಿಕ ವಿಕೋಪ ಪರಿಹಾರ ಯೋಜನೆ 2019-20

Bill No. : 285/2020-21

Amount : 200,000.00

Name Of Work (As per Sactioned Estimate) : ಉಡುಪಿ ಜಿಲ್ಲೆ ಕುಂದಾಪುರ ತಾಲೂಕು ಹೆಂಗವಳ್ಳಿ ಗ್ರಾಮ ಪಂಚಾಯತ್ ವ್ಯಾಪ್ತಿಯ ಸ. ಹಿ. ಪ್ರಾ. ಶಾಲೆ ಹೆಂಗವಳ್ಳಿ ಇದರ ಕಟ್ಟಡದ ದುರಸ್ತಿ ಕಾಮಗಾರಿ.

Estimate Amount : 200,000.00

Date of Commencement : 24-03-20

Date of Completion : 08-09-20

Administrative Approval No. : ಸಿಆರ್:ಸಿಎಎಲ್ : ಪ್ರಾ.ವಿ: 336/2019-20/49832 Date: 08-12-19

Amount Rs. : 200,000.00

Technical Sanction No. : 536/2019-20 Date: 20-03-20

Amount Released for the work up to date from the entrusting agency `.

Certified the works referred to above have been checked and the measurements taken by me on 09-09-2020 and recorded on Pages 01- 03 Of Measurement Book no 913Has been correctly complied and work has been satisfactorily executed.

14

Project Engineer
Udupi Nirmithi Kendra.(R)

Certified that the Running Account Bill no. 285 Has been Checked by me are found correct. The work has been satisfactorily executed.

Moodlakatte Institute of Technology
Moodlakatte, Kundapura - 576217
Udupi Dist, Karnataka

Project Director
Udupi Nirmithi Kendra.(R)



Moodlakatte Institute of Technology

(A Unit of Moodlakatte Nagarathna Bhujanga Shetty Trust (R.))

(Approved by AICTE, New Delhi & Affiliated to V.T.U., Belagavi)

Moodlakatte - 576 217, Kundapura Taluk, Udupi District, Karnataka




Ref.No.: MITK/CV/CW/20-21/NK/10/015


Date : 15/10/2020


INSPECTION/ WORK COMPLETION REPORT (1st & Final Bill)

1	Name of the ULB	NIRMITHI KENDRA (UDUPI) NATURAL DISASTER GRANT 2019-20
2	Name of the Work/ Scheme	REPAIRING WORK OF GOVT. HIGHER PRIMARY SCHOOL BUILDING AT HENGAVALI G.P, KUNDAPURA TALUK, UDUPI DISTRICT.
3	Administrative Approval No: / Agreement No.	CR:CAL:PRA.V: 336/2019-20/49832 Dtd: 08/12/2019
4	Technical Sanction No/ DER No.	536/2019-20
5	Estimate Cost	Rs.2,00,000.00/-
6	Bill Amount	Rs.2,00,000.00/-
7	Name of the ULB Engineer present at site	Mr. GANESH PRASAD SHETTY
8	Name of the contractor	NIRMITHI KENDRA UDUPI
9	Name of the inspecting consultants Engineer	Mr. SUBRAMANYA P
10	Date of commencement of the work	24/03/2020
11	Date of Completion	08/09/2020
12	Date of the Inspection	11/09/2020
13	Status of the Work	COMPLETED
14	Details of Quality tests carried out by consultants	Inspected the work no major deficiency were found and quality of the work is satisfactory.
15	Photographs of the works along with date of inspection on the photo	Attached
16	Consultant clear opinion regarding acceptance of the quality of work.	We have inspected the site and observed that work is done according to the norms and specification mentioned
17	If the quality of work is not up to the satisfactory, the consultants suggestions for rectifications/ redoing	No Suggestions, Work is done satisfactorily
18	Measurement Book No. in which the measurement recorded	MB No-913 Pg No – 01-03
19	Opinion of the Third Party agency regarding measurement	Measurement checked as per the estimation copy and found to be correct.


Principal & Head, Civil Department
MOODLAKATTE INSTITUTE OF TECHNOLOGY
Moodlakatte, Kundapura - 576 217
Udupi Dist., Karnataka


Principal
Moodlakatte Institute of Technology
Moodlakatte, Kundapura - 576217
Udupi Dist, Karnataka





UDUPI NIRMITHI KENDRA .(R)

D.C.Office,Manipal RUNNING ACCOUNT BILL

Date: 18-09-20

FIRST & FINAL BILL

Name of Project : ಪ್ರಾಕೃತಿಕ ವಿಕೋಪ ಪರಿಹಾರ ಯೋಜನೆ 2019-20

Bill No. : 286/2019-20

Amount : 200,000.00

Name Of Work (As per Sactioned Estimate) : ಉದುವಿ ಜಿಲ್ಲೆ ಕುಂದಾಪುರ ತಾಲೂಕು ಸ ಹಿ ಪ್ರಾ ಶಾಲೆ ಅರಸಮ್ಮಕಾನು ಶೇಡಿಮನೆ ಗ್ರಾಮ ಕುಂದಾಪುರ ವಲಯ ಇದರ ಶೌಚಾಲಯ ದುರಸ್ತಿ ಕಾಮಗಾರಿ.

Estimate Amount : 200,000.00

Date of Commencement : 24-03-20

Date of Completion : 03-09-20

Administrative Approval No. : ಸಿಆರ್:ಸಿಎಎಲ್ : ಪ್ರಾ.ವಿ: 336/2019-20/49836

Date: 08-12-19

Amount Rs. : 200,000.00

Technical Sanction No. : 638/2019-20

Date: 21-03-20

Amount Released for the work up to date from the entrusting agency `.

Certified the works referred to above have been checked and the measurements taken by me on 4-09-2020 and recorded on Pages 01- 03 Of Measurement Book no 914 Has been correctly complied and work has been satisfactorily executed.

Project Engineer
Udupi Nirmithi Kendra.(R)

Certified that the Running Account Bill no. 286 Has been Checked by me are found correct. The work has been satisfactorily executed.


Principal
Moodlakatte Institute of Technology
Moodlakatte, Kundapura - 576217
Udupi Dist, Karnataka

Project Director
Udupi Nirmithi Kendra.(R)



Moodlakatte Institute of Technology

(A Unit of Moodlakatte Nagarathna Bhujanga Shetty Trust (R.))

(Approved by AICTE, New Delhi & Affiliated to V.T.U., Belagavi)

Moodlakatte - 576 217, Kundapura Taluk, Udupi District, Karnataka

A WIDE
HORIZON OF
OPPORTUNITIES

Ref.No.: MITK/CV/CW/20-21/NK/10/010

Date : 13/10/2020


INSPECTION/ WORK COMPLETION REPORT (1st & Final Bill)

1	Name of the ULB	NIRMITHI KENDRA (UDUPI) NATURAL DISASTER GRANT 2019-20
2	Name of the Work/ Scheme	REPAIRING WORK OF TOILET FOR GOVT. HIGHER PRIMARY SCHOOL AT ARASAMAKHANU SHEDIMANE VILLAGE, KUNDAPURA TALUK, UDUPI DISTRICT.
3	Administrative Approval No. / Agreement No.	CR:CAL:PRA.V: 336/2019-20/49836 Dtd: 08/12/2019
4	Technical Sanction No/ DER No.	638/2019-20
5	Estimate Cost	Rs.2,00,000.00/-
6	Bill Amount	Rs.2,00,000.00/-
7	Name of the ULB Engineer present at site	Mr. GANESH PRASAD SHETTY
8	Name of the contractor	NIRMITHI KENDRA UDUPI
9	Name of the inspecting consultants Engineer	Mr. PRASAD GAONKAR
10	Date of commencement of the work	24/03/2020
11	Date of Completion	03/09/2020
12	Date of the Inspection	11/09/2020
13	Status of the Work	COMPLETED
14	Details of Quality tests carried out by consultants	Inspected the work no major deficiency were found and quality of the work is satisfactory.
15	Photographs of the works along with date of inspection on the photo	Attached
16	Consultant clear opinion regarding acceptance of the quality of work.	We have inspected the site and observed that work is done according to the norms and specification mentioned
17	If the quality of work is not up to the satisfactory, the consultants suggestions for rectifications/ redoing	No Suggestions, Work is done satisfactorily
18	Measurement Book No. in which the measurement recorded	MB No-914 Pg No - 01-03
19	Opinion of the Third Party agency regarding measurement	Measurement checked as per the estimation copy and found to be correct.

HOD, Civil Department
MOODLAKATTE INSTITUTE OF TECHNOLOGY
Moodlakatte, Kundapura - 576 217
Udupi Dist., Karnataka

Inspection Engineer

Principal
Moodlakatte Institute of Technology
Moodlakatte, Kundapura - 576217
Udupi Dist, Karnataka



UDUPI NIRMITHI KENDRA .(R)
D.C.Office,Manipal
RUNNING ACCOUNT BILL

Date: 18-09-20

FIRST & FINAL BILL

Name of Project : ಪ್ರಾಕೃತಿಕ ವಿಕೋಪ ಪರಿಹಾರ ಯೋಜನೆ 2019-20

Bill No. : 287/2020-21

Amount : 200,000.00

Name Of Work (As per Sactioned Estimate) : ಉಡುಪಿ ಜಿಲ್ಲೆಯ ಉಡುಪಿ ತಾಲೂಕಿನ ಹಾವಂಜೆ ಗ್ರಾಮ ಪಂಚಾಯತ್ ವ್ಯಾಪ್ತಿಯ ದೊಂಪದಕುಮೇರಿ ಅಂಗನವಾಡಿ ದುರಸ್ತಿ ಕಾಮಗಾರಿ.

Estimate Amount : 200,000.00

Date of Commencement : 13-02-20

Date of Completion : 12-09-20

Administrative Approval No. : ಪ್ರಾ.ವಿ.ಪ್ರಾ.ವಿ.:336/2019-20/49832

Date: 04-12-19

Amount Rs. : 200,000.00

Technical Sanction No. : 421/2019-20

Date: 12-02-20

Amount Released for the work up to date from the entrusting agency `.

Certified the works referred to above have been checked and the measurements taken by me on 14-09-2020 and recorded on Pages 01- 09 Of Measurement Book no 915 Has been correctly complied and work has been satisfactorily executed.

Project Engineer
Udupi Nirmithi Kendra.(R)

Certified that the Running Account Bill no. 287/2020-21 Has been Checked by me are found correct. The work has been satisfactorily executed.

Principal
Moodlakatte Institute of Technology
Moodlakatte, Kundapura - 576217
Udupi Dist, Karnataka

Project Director
Udupi Nirmithi Kendra.(R)

Moodlakatte Institute of Technology

(A Unit of Moodlakatte Nagarathna Bhujanga Shetty Trust (R.))



(Approved by AICTE, New Delhi & Affiliated to V.T.U., Belagavi)


Moodlakatte - 576 217, Kundapura Taluk, Udupi District, Karnataka


Ref.No.: MITK/CV/CW/20-21/NK/10/008




INSPECTION/ WORK COMPLETION REPORT (1st & Final Bill)

1	Name of the ULB	NIRMITHI KENDRA (UDUPI) NATURAL DISASTER GRANT 2019-20
2	Name of the Work/ Scheme	REPAIRING WORK OF ANGANAVADI BUILDING AT DOMPADAKUMERI, HAVANJE G.P., UDUPI TALUK & DISTRICT.
3	Administrative Approval No: / Agreement No.	CR:CAL:PRA.V: 336/2019-20/41832 Dtd: 04/12/2019
4	Technical Sanction No/ DER No.	421/2019-20
5	Estimate Cost	Rs.2,00,000.00/-
6	Bill Amount	Rs.2,00,000.00/-
7	Name of the ULB Engineer present at site	Mr. KISHORE KUMAR
8	Name of the contractor	NIRMITHI KENDRA UDUPI
9	Name of the inspecting consultants Engineer	Mr. SUBRAMANYA P
10	Date of commencement of the work	13/02/2020
11	Date of Completion	12/09/2020
12	Date of the Inspection	06/10/2020
13	Status of the Work	COMPLETED
14	Details of Quality tests carried out by consultants	Inspected the work no major deficiency were found and quality of the work is satisfactory.
15	Photographs of the works along with date of inspection on the photo	Attached
16	Consultant clear opinion regarding acceptance of the quality of work.	We have inspected the site and observed that work is done according to the norms and specification mentioned
17	If the quality of work is not up to the satisfactory, the consultants suggestions for rectifications/ redoing	No Suggestions, Work is done satisfactorily
18	Measurement Book No. in which the measurement recorded	MB No-915 Pg No - 01-09
19	Opinion of the Third Party agency regarding measurement	Measurement checked as per the estimation copy and found to be correct.


Principal
Moodlakatte Institute of Technology
Moodlakatte, Kundapura - 576 217
Udupi Dist., Karnataka


Principal
Moodlakatte Institute of Technology
Moodlakatte, Kundapura - 576 217
Udupi Dist., Karnataka





Moodlakatte Institute of Technology

(A Unit of Moodlakatte Nagarathna Bhujanga Shetty Trust (R.))

(Approved by AICTE, New Delhi & Affiliated to V.T.U., Belagavi)

Moodlakatte - 576 217, Kundapura Taluk, Udupi District, Karnataka

Ref.No.: MITK/CV/CW/2018-19/KRIDL/04/025



INSPECTION/ WORK COMPLETION REPORT

TO,
Assistant Director,
K.R.I.D.L, Udupi

Respected Sir,

Subject: Report of quality test conducted for the project under Varahi Scheme, Under Udupi Jurisdiction through the office of Assistant Director, K.R.I.D.L, Udupi

Ref: Honorable District Commissioner Office transaction letter
No:EE/KRDIDL/UDUPI/TS/2016-17/-1215/2017-18 dtd 19/03/2018

Quality test has been conducted at various stages during the progress of the work
DEVELOPMENT WORK OF NEAR SUDHAKAR HOUSE ROAD AT YELLURU G.P, UDUPITALUK & DISTRICT. Under Jurisdiction through Executive Engineer, K.R.I.D.L, Udupi.

During the inspection, necessary technical suggestions have been given .Inspection of the materials at the site and Quality test has been conducted. We have inspected the site and observed that Earth work excavation has been completed and laying of WBM Sub base has been commenced. Inspection has been carried out in the presence of Assistant Director KRIDL, Udupi and Assistant Engineer, T.F.C, Udupi of the project. Work has been completed satisfactorily according to the information and estimation submitted to the department.

<u>Sl No</u>	<u>Name of the Project</u>	<u>Estimated Cost</u>	<u>Technical Sanction No</u>
1	DEVELOPMENT WORK OF NEAR SUDHAKAR HOUSE ROAD AT YELLURU G.P, UDUPITALUK & DISTRICT	Rs.5,00,000.00	84/2018-19DtD 26.06.2018


HOD, Civil Department, Civil Department
MOODLAKATTE INSTITUTE OF TECHNOLOGY
Moodlakatte, Kundapura - 576 217
Udupi Dist, Karnataka


Principal
Moodlakatte Institute of Technology
Moodlakatte, Kundapura - 576217
Udupi Dist, Karnataka



ಎಲ್ಲೂರು ಗ್ರಾ.ಪಂ ಬಳಿ ಸುಧಾಕರ ಮನೆಗೆ ಹೋಗುವ ರಸ್ತೆ ಅಭಿವೃದ್ಧಿ

TS No-84 -2018/19, D-26.06.2018, EST-5.00

2 Excavation for road way using manual means

Formation	1 x	90.50	4.00	0.20	=	72.40
						72.40 Cum

2 Wet mix

0-30	1 x	30.00	$\frac{3.90 + 3.90}{2} \times$	0.10	=	11.70
------	-----	-------	--------------------------------	------	---	-------

30-60	1 x	30.00	$\frac{3.90 + 3.90}{2} \times$	0.10	=	11.70
-------	-----	-------	--------------------------------	------	---	-------

60-90.5	1 x	30.50	$\frac{3.90 + 3.90}{2} \times$	0.10	=	11.90
---------	-----	-------	--------------------------------	------	---	-------

35.30 Cum

3 M30

0-30	1 x	30.00	$\frac{3.90 + 3.90}{2} \times$	0.15	=	17.55
------	-----	-------	--------------------------------	------	---	-------

30-60	1 x	30.00	$\frac{3.90 + 3.90}{2} \times$	0.15	=	17.55
-------	-----	-------	--------------------------------	------	---	-------

60-90.5	1 x	30.50	$\frac{3.90 + 3.90}{2} \times$	0.15	=	17.84
---------	-----	-------	--------------------------------	------	---	-------

52.94 Cum

4 EMBANKMENT

2.0 x	90.50	0.35	0.20	=	12.86 Cum
-------	-------	------	------	---	------------------

Principal

Moodlakatte Institute of Technology
Moodlakatte, Kundapura - 576217
Udupi Dist, Karnataka

Ref.No.: MITK/CV/CW/2018-19/KRIDL/04/026

Date: 30/04/2019

INSPECTION/ WORK COMPLETION REPORT

TO,
Assistant Director,
K.R.I.D.L, Udupi

Respected Sir,

Subject: Report of quality test conducted for the project under Varahi Scheme, Under Udupi Jurisdiction through the office of Assistant Director, K.R.I.D.L, Udupi

Ref: Honorable District Commissioner Office transaction letter
No:EE/KRIDL/UDUPI/TS/2016-17/-1215/2017-18 dtd 19/03/2018

Quality test has been conducted at various stages during the progress of the work
DEVELOPMENT WORK OF ROAD NEAR AMBIKA MILL TO SC SOMASHEKAR HOUSE ROAD AT KATAPADI G.P, UDUPITALUK & DISTRICT. Under Jurisdiction through Executive Engineer, K.R.I.D.L, Udupi.

During the inspection, necessary technical suggestions have been given .Inspection of the materials at the site and Quality test has been conducted. We have inspected the site and observed that Earth work excavation has been completed and laying of WBM Sub base has been commenced. Inspection has been carried out in the presence of Assistant Director KRIDL, Udupi and Assistant Engineer, T.F.C, Udupi of the project. Work has been completed satisfactorily according to the information and estimation submitted to the department.

<u>Sl No</u>	<u>Name of the Project</u>	<u>Estimated Cost</u>	<u>Technical Sanction No</u>
1	DEVELOPMENT WORK OF ROAD NEAR AMBIKA MILL TO SC SOMASHEKAR HOUSE ROAD AT KATAPADI G.P, UDUPITALUK & DISTRICT	Rs.5,00,000.00	55/2018-19DtD 26.06.2018

Shan
HOD, Civil Department
HOD, Civil Department
MOODLAKATTE INSTITUTE OF TECHNOLOGY
Moodlakatte, Kundapura - 576 217
Udupi Dist., Karnataka

Principal
Principal

Inspection Engineer
Inspection Engineer
Inspection Engineer

Moodlakatte Institute of Techno...
Moodlakatte, Kundapura - 576217
Udupi Dist, Karnataka

ಕಟಪಾಡಿ ರಾ.ಹೆ ಅಂಬಿಕಾ ಮಿಲ್ ಬಳಿಯಿಂದ ಪ.ಜಾತಿ ನೋಮಶೇಖರ ರವರ ಮನೆಗೆ
ಹೋಗುವ ರಸ್ತೆ ಅಭಿವೃದ್ಧಿ

TS No-55 -2018/19, D-26.06.2018, EST-5.00

2 Excavation for road way using manual means

Formation	1 x	105.00	3.60	0.20	=	75.60
						75.60 Cum

2 Wet mix

0-30	1 x	30.00	$\frac{3.50 + 3.50}{2} \times$	0.10	=	10.50
------	-----	-------	--------------------------------	------	---	-------

30-60	1 x	30.00	$\frac{3.50 + 3.50}{2} \times$	0.10	=	10.50
-------	-----	-------	--------------------------------	------	---	-------

60-90	1 x	30.00	$\frac{3.50 + 3.50}{2} \times$	0.10	=	10.50
-------	-----	-------	--------------------------------	------	---	-------

90-105	1 x	15.00	$\frac{3.50 + 3.50}{2} \times$	0.10	=	5.25
--------	-----	-------	--------------------------------	------	---	------

36.75 Cum

3 M30

0-30	1 x	30.00	$\frac{3.50 + 3.50}{2} \times$	0.15	=	15.75
------	-----	-------	--------------------------------	------	---	-------

30-60	1 x	30.00	$\frac{3.50 + 3.50}{2} \times$	0.15	=	15.75
-------	-----	-------	--------------------------------	------	---	-------

60-90	1 x	30.00	$\frac{3.50 + 3.50}{2} \times$	0.15	=	15.75
-------	-----	-------	--------------------------------	------	---	-------

90-105	1 x	15.00	$\frac{3.50 + 3.50}{2} \times$	0.15	=	7.88
--------	-----	-------	--------------------------------	------	---	------

55.13 Cum

4 EMBANKMENT

	2.0 x	105.00	0.30	0.25	=	15.99 Cum
--	-------	--------	------	------	---	------------------



Principal
Moodlakatte Institute of Technology
Moodlakatte, Kundapura - 576217
Udupi Dist, Karnataka

Ref.No.: MITK/CV/CW/2018-19/KRIDL/04/027

Date: 30/04/2019

INSPECTION/ WORK COMPLETION REPORT

TO,
Assistant Director,
K.R.I.D.L, Udupi

Respected Sir,

Subject: Report of quality test conducted for the project under Varahi Scheme, Under Udupi Jurisdiction through the office of Assistant Director, K.R.I.D.L, Udupi

Ref: Honorable District Commissioner Office transaction letter
No:EE/KRIDL/UDUPI/TS/2016-17/-1215/2017-18 dtd 19/03/2018

Quality test has been conducted at various stages during the progress of the work
DEVELOPMENT WORK OF ROAD FROM MATTARU SOCIETY TO ARABBI KATTAKKAGI NINJURU ROAD AT SHIRVA G.P, UDUPITALUK & DISTRICT. Under Jurisdiction through Executive Engineer, K.R.I.D.L, Udupi.

During the inspection, necessary technical suggestions have been given. Inspection of the materials at the site and Quality test has been conducted. We have inspected the site and observed that Earth work excavation has been completed and laying of WBM Sub base has been commenced. Inspection has been carried out in the presence of Assistant Director KRIDL, Udupi and Assistant Engineer, T.F.C, Udupi of the project. Work has been completed satisfactorily according to the information and estimation submitted to the department.

Sl No	Name of the Project	Estimated Cost	Technical Sanction No
1	DEVELOPMENT WORK OF ROAD FROM MATTARU SOCIETY TO ARABBI KATTAKKAGI NINJURU ROAD AT SHIRVA G.P, UDUPITALUK & DISTRICT	Rs.5,00,000.00	104/2018-19DtD 26.06.2018

[Signature]
HOD, Civil Department

Professor & Head, Civil Department

MOODLAKATTE INSTITUTE OF TECHNOLOGY

Moodlakatte, Kundapura - 576 217

Udupi Dist., Karnataka

[Signature]
Principal

Moodlakatte Institute of Technology

Moodlakatte, Kundapura - 576217

Udupi Dist, Karnataka

[Signature]
Inspection Engineer

ಶಿರ್ವ ಮಟ್ಟಾರು ಸೊಸೈಟಿಯಿಂದ ಅರಬ್ಬಿ ಕಟ್ಟಕ್ಕಾಗಿ ನಿಂಜೂರುವರೆಗೆ ರಸ್ತೆ ಅಭಿವೃದ್ಧಿ

TS No- 104-2018/19, D-26.06.2018, EST-5.00

- 2 Water Bound Macadam-GRADE II
 Grade II 1 x 267.00 x 3.14 x 0.075 = 62.88
 Pot Hole Filling 15% 9.43 Cum
- 3 Water Bound Macadam -GRADE III
 Grade III 1 x 267.00 x 3.14 x 0.075 = 62.88
 Pot Hole Filling 15% 9.43 Cum
- 4 KSRRB M500-6. Providing and applying primer coat
 (PWD SR 2016-17, Page 161, Item No.21.6)
 1 x 267.00 x 3.14 = 838.38
 Pot Hole Filling 15% 125.76 Sqm
- 5 Providing and applying tack coat
 (PWD SR 2016-17, Page 161, Item No.21.7)
 1 x 267.00 x 3.14 = 838.38
 Pot Hole Filling 15% 125.76 Sqm
- 6 Providing and laying open graded premix carpet
 1 x 267.00 x 3.14 = 838.38
 Pot Hole Filling 15% 125.76 Sqm
- 7 Providing and laying seal coat sealing
 1 x 267.00 x 3.14 = 838.38
 Pot Hole Filling 15% 125.76 Sqm
- 8 Construction of Subgrade
 Shoulders 2 x 267.00 x 0.30 x 0.15 = 24.39
 24.39 Cum



Principal
 Moodlakatte Institute of Technology
 Moodlakatte, Kundapura - 576217
 Udupi Dist, Karnataka